


# CLM-110-HU0136 Kit Components



1. Basin CPC Connector
2. Universal Luer Connector

## WARNINGS AND CAUTIONS

Hookups must be periodically inspected to ensure that their functionality is not impaired. Check for damage/worn connectors, missing/damaged components, kinked/blocked tubing and other damage.

### DO NOT AUTOCLAVE.

Check to make sure that connections remain firmly attached during the disinfection cycle and until the completion of the cycle to ensure proper high level disinfection.

Refer to endoscope manufacturer's instruction guide for more information.

**NOTE:** If you have any questions regarding this hookup please contact your service technician or contact Medivators Customer Support at 1.800.444.4729 or 763.553.3300.

[www.minntech.com/medivators](http://www.minntech.com/medivators)



Manufactured in the USA by:  
**MEDIVATORS**  
REPROCESSING SYSTEMS  
A Minntech Corporation Business Group

Minntech Corporation  
14605 28th Avenue North  
Minneapolis, MN 55447 USA  
Phone: (763) 553-3300  
Toll Free: (800) 328-3340  
Fax: (763) 553-3387  
website: [www.minntech.com](http://www.minntech.com)

Minntech BV  
Sourethweg 11  
6422PC Heerlen  
The Netherlands  
Phone: +31 45 5 471 471  
Fax: +31 45 5 429 695  
email: [info@minntechbv.com](mailto:info@minntechbv.com)


Minntech Asia/Pacific  
438 Alexandra Road  
#03-01 Alexandra Point  
Singapore 119958  
Phone: +65 6227 9698  
Fax: +65 6225 6848

Minntech Beijing Representative Office  
AVIC PLAZA, Room 1508B  
No. 10 Yi Dongsanhuan Zhonglu,  
Beijing 100022, China  
Phone: +8610 6567 8446  
Fax: +8610 6567 8445



© 2009, MINNTECH CORPORATION  
50097-135/A

# CLM-110-HU0136 Kit Components



1. Basin CPC Connector
2. Universal Luer Connector

## WARNINGS AND CAUTIONS

Hookups must be periodically inspected to ensure that their functionality is not impaired. Check for damage/worn connectors, missing/damaged components, kinked/blocked tubing and other damage.

### DO NOT AUTOCLAVE.

Check to make sure that connections remain firmly attached during the disinfection cycle and until the completion of the cycle to ensure proper high level disinfection.

Refer to endoscope manufacturer's instruction guide for more information.

**NOTE:** If you have any questions regarding this hookup please contact your service technician or contact Medivators Customer Support at 1.800.444.4729 or 763.553.3300.

[www.minntech.com/medivators](http://www.minntech.com/medivators)



Manufactured in the USA by:  
**MEDIVATORS**  
REPROCESSING SYSTEMS  
A Minntech Corporation Business Group

Minntech Corporation  
14605 28th Avenue North  
Minneapolis, MN 55447 USA  
Phone: (763) 553-3300  
Toll Free: (800) 328-3340  
Fax: (763) 553-3387  
website: [www.minntech.com](http://www.minntech.com)

Minntech BV  
Sourethweg 11  
6422PC Heerlen  
The Netherlands  
Phone: +31 45 5 471 471  
Fax: +31 45 5 429 695  
email: [info@minntechbv.com](mailto:info@minntechbv.com)

Minntech Asia/Pacific  
438 Alexandra Road  
#03-01 Alexandra Point  
Singapore 119958  
Phone: +65 6227 9698  
Fax: +65 6225 6848

Minntech Beijing Representative Office  
AVIC PLAZA, Room 1508B  
No. 10 Yi Dongsanhuan Zhonglu,  
Beijing 100022, China  
Phone: +8610 6567 8446  
Fax: +8610 6567 8445



© 2009, MINNTECH CORPORATION  
50097-135/A